



EQUIPMENT RECALL AND PROHIBITION (ERAP) CIRCULAR 01/2018
File: D02273

OCTOBER 2018

RECALL OF STANDARD STAUN TYRE DEFLATION KITS

It has been brought to our attention that the Standard Staun Tyre Deflators supplied by FRSA have been incorrectly pre-set.



The Staun Tyre Deflation Kits need to be returned by courier (at FRSA's cost). FRSA will recalibrate each kit to the correct 26 PSI pre-set and conduct a test before returning to station. Replacement kits will not be provided in the interim.

Please send the Staun Tyre Deflation Kits to:

Fire Rescue Safety Australia
Attn: Angela Muir
17 Millrose Drive
Malaga WA 6090

LLOYD BAILEY AFSM
DEPUTY COMMISSIONER OPERATIONS

| Target Audience: All operational personnel with tyre deflation kits. | | | | |
|--|-------------|---------------|-----------------------------|------------------------------|
| A | B | C | D | Vol |
| O.I.C. is to communicate content to all relevant personnel under their command, discuss implications, and sign appropriate box above. Once completed Circulars shall be filed on station and forwarded to Information Resources at the end of each financial year. | | | | |
| OC-01-18 | Issue Date: | Removal Date: | Contact: | Fleet and Equipment Services |
| Page 1 of 1 | Oct 2018 | Oct 2019 | Ric.MONASTRA@dfes.wa.gov.au | |